

1996 SHUTTLELIFT 3330e 8.5t Carrydeck Crane mfg in USA

This Shuttlelift 3330e carry deck crane was involved in a partial rollover related incident. The damage was limited to primarily the operator's cab and hydraulic oil tank. The crane is structurally sound. Service personnel have stated the Cummins 4B3.9 and power train components are fully operational. Tires are Westlake 10.00x 15 with 4-ply rating. Recent components upgrades consisted of new swing bearing and hoist cable. The machine is complete with boom extension (jib), hookblock, manuals, some spares parts, etc.

We have fabricated a new operator's cab and hydraulic oil tank which has not yet been installed.

We purchased this machine in 2008 with the intention of rebuilding it for our own fleet. However time restraints due to other business pressures kept us from completing the rebuild.

The machine is in generally good condition - had been well maintained and, is worth the time to rebuild..

www.deckrane.com

